Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2311Work Order Type: WeatherizationAudit Name: 14014SO2311

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2311 FAYETTEVILLE, TN 37334

Alt. Client ID: LINCOLN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Client Name:
Client ID: 14014SO2311
Alt. Client ID: LINCOLN

Work Order (Bid Form)
Work Order Name: 14014SO2311
Report Run On: 5/21/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 5

Measures

Measure 1 DW Comment	H Pipe Insulation			Componen				Inspected
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Ofv	Actual Unit Cost	Total
1 Insulation	DEW Pipe Insulation	Each	<i>Qiy</i> 1	Unit Cost	I Olai	Qty	Omit Cost	I Otal
i insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail][1			1		
			Measur	e Sub Total:] ,	Sub Total:	
Measure 2 Floo	or Ins. R-19			Component Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1023					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1023					
Other Detail						1		
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								

Report Run On: 5/21/2010

	TRATION REDUCTION	N .		Componen	ts			Inspected
REGIST 2. W/S F 3. W/S A 4. W/S S	DUCT WORK / USE M. ERS TO READ 1.0 OR FRONT DOOR AND D/S BACK DOOR A SIDE DOOR ALL MISSING WINDOW	LESS AND INST				N -		
			Estimated				Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Miscellaneous Supplies	INFILTRATION REDUCTION	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
]	Sub Total:	
							Siin Intai:	
Field Notes:			Measur	e Sub Total:			ous rotuin	
Measure 4 Fix II	mproper Venting (Cloti			Componen				Inspected
Measure 4 Fix II		hes Dryer)	Componen Estimated	<u>'</u>		Actual	
Measure 4 Fix II Comment # Material / Labor	mproper Venting (Clot) Description / Comment Metal Flex			Componen		Qty		Inspected Total
Measure 4 Fix II Comment Material / Labor Health and Safety Items	Description / Comment	hes Dryer) Units	Qty	Componen Estimated	<u>'</u>		Actual	
Measure 4 Fix In Comment # Material / Labor 1 Health and Safety Items	Description / Comment Metal Flex	hes Dryer Units Each	Qty 1	Componen Estimated	<u>'</u>		Actual	
Measure 4 Fix In Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Metal Flex	hes Dryer Units Each	Qty 1	Componen Estimated	<u>'</u>		Actual	
Measure 4 Fix In Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Metal Flex	hes Dryer <i>Units</i> Each Hour	Qty 1 1	Componen Estimated	<u>'</u>	Qty	Actual	

Report Run On: 5/21/2010

Measure 5 PressureRelief Piping Needed Comment EXTEND THROUGH FOUNDATION			Componen	ts	Inspecte				
	The second of th			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
 Health and Safety Items 	Pressure relief piping	Each	1						
2 Labor	Labor	Hour	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:									
Measure 6 Smo	oke Detector is Needed			Componen				Inspecte	
Measure 6 Smo		Units	Qtv	Estimated	1	Qtv	Actual		
Measure 6 Smo	Description / Comment	<i>Units</i> Each	Qty 1	•		Qty		Inspecte	
Measure 6 Smc Comment # Material / Labor 1 Health and Safety	Description / Comment			Estimated	1	Qty	Actual		
Measure 6 Smo Comment # Material / Labor 1 Health and Safety Items	Description / Comment Smoke / Carbon detector	Each	1	Estimated	1	Qty	Actual		
Measure 6 Smo Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Smoke / Carbon detector	Each	1	Estimated	1	Qty	Actual		
Measure 6 Smo Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Smoke / Carbon detector	Each	1 1	Estimated	1		Actual		

Report Run On: 5/21/2010

	por Barrier Needed asement/Crawlspace)			Componen	ts		ı	nspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	